

CONSUMER SAFETY NOTICE

SELECT STOHLQUIST INFANT AND CHILD PFDS

Stohlquist WaterWare, Inc. is conducting a voluntary product replacement of select Stohlquist Infant and Child PFDs. If you have purchased a Stohlquist Infant or Child PFD after March 29th 2017, it will need to be inspected to determine if it needs to be returned for replacement. Stohlquist is concerned that defective beads attached to the handle of the PFD can break off and become a choking hazard. While there have been reports of the beads breaking off, there have not been any reported injuries. Stohlquist believes that issuing a voluntary safety notice is the safe and prudent thing to do.




Lot numbers can be found at the bottom of the USCG or ULC approval label printed on the interior of the PFD.

Affected Lot Numbers

4001164	4004164	4008164
4002164	4005164	4007164
4003164	4006164	4015164
5001171	5002171	5003171

Only PFDs marked on the inside with these Lot Numbers have defective beads.



Defective Beads can be visually identified by their shiny appearance and quantity of 6 on the PFD handle. PFDs with 7 matte beads on the handle are not affected.

REMEDY: Consumers should immediately stop using their PFD if it is marked with one of the above lot numbers and bring the PFD to your nearest authorized Stohlquist Retailer. They will be able to replace your PFD for you. The replacement is made under warranty and you will not incur any charges.

CONSUMER CONTACT - If you identify a defective item as described above, please email your name, address, telephone number, and which item you have to info@stohlquist.com. We will contact you to arrange a replacement as soon as possible.



**Note: Replacement product will NOT have beads on the handles. As shown here.*